

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




FIG. 1




FIG. 3




FIG. 2

103




FIG. 4




FIG. 5






FIG. 6






FIG. 9






FIG. 10





FIG. 11






FIG. 13





FIG. 14







FIG. 16








FIG. 18




FIG. 19




FIG. 20

12<sup>c</sup> ↗





FIG. 21



122





FIG. 23





FIG. 24




FIG. 25








FIG. 26












FIG. 31





FIG. 32



3361

37/




FIG 34




FIG 35




FIG. 36

145

146





FIG-37



# Snap Prox Sensor



Base Corporation  
 The Mountain  
 Framingham, MA 01701  
 Neil Gelfond

Page Size: A

February 19, 2004

Page 1 of 2

FIG. 38

147

